

# CCW EasyCast HD Cleaning & Post Curing Instructions

#### Cleaning your printed part(s)

#### Required Items:

Isopropyl alcohol (IPA) 99% or methyl hydrate and compressed Air

Step 1. Remove printed parts(s) from build plate.

Step 2. Submerge part(s) in IPA 99% or Methyl hydrate bath.

Step 3. Shake vigorously in bath solution for 30 to 40 seconds. Remove and inspect part(s) for residual resin.

Step 4. If part(s) still have residual resin, repeat step 3 as necessary, until all residue is removed.

Step 5. Take part(s) and rinse under HOT WATER for about 30-40 seconds and then under COLD WATER.

Step 6. Use compress air to blow dry part(s). Inspect part(s) for shiny patches. Repeat Step 3 and Step 5 if you see shiny patches. ALL AREAS OF PARTS SHOULD HAVE A MATTE FINISH

\*\*\*\*\*DO NOT LEAVE PART(S) IN METHYLHYDRATE OR IPA BATH FOR LONG TIMES AS IT MAY CAUSE CRACKS IN THE PART\*\*\*\*\*

### Curing your printed part(s)

#### Required Items:

Glass Bowl, glycerin and a minimum 60 watt 390-405 UV curing chamber.

Step 1. Place part(s) in a glass bowl

Step 2. Fill glass bowl with glycerin covering the printed part(s).

Step 3. Place bowl of glycerin with printed part(s) in UV curing chamber

Step 4. Turn on UV chamber for approx. 30 to 40 minutes. Curing times may vary based on type of curing chamber used and part density.

Step 5. Turn part(s) every 10 minutes so that the UV light can be absorbed by all surface areas.


Step 6. Part(s) should be extremely rigid and brittle. Squeeze part(s) in a variety of directions to ensure the parts are full cured. If the part(s) are still soft, place back into the UV curing chamber and cure for an additional 10 minutes.

Step 7. Repeat step 6 to achieve desired stiffness.

Step 8. Wash part(s) in HOT WATER and then COLD WATER and then use compressed air to completely dry off part(s).

Step 9. Submerge part(s) in CLEAN IPA for 30 seconds and dry.

## Two Recommended Burnout Schedules



<sup>\*</sup>All ramp rates set at 28 F / 2 C per minute

<sup>\*</sup>Burnout schedule based on phosphate invesment and verifed by Resinworks3D. Exact schedule may vary slightly based on casting equipment used.